

# *Spot the Hazards*



**WORK SAFE BC**

*"Safety is a core value and business priority"*





# Spot the Hazards



The machine may be on, as indicated by the green light. If the machine is not required to complete the weld it should be locked out.

The worker isn't hearing the proper welding head protection.

The worker is working at face level, and has poor posture. He's also not wearing proper PPE for welding, like a leather apron.

The rags should be stored further from the hot work, and in a container with a lid. If they're contaminated with flammable materials., they should be placed in a fire-safe disposal bin.

There are no fire extinguishers in the immediate area.

The cords at the worker's feet are a tripping hazard.

This can is open and in range of the welding, and may be a fire or explosion hazard.



*"Safety is a core value and business priority"*

