


Electrical Safety

What type of clothing is best practice within the mill?



Did you know that synthetic clothing can melt during an arc flash event and therefore should be avoided within the Mill.

Wear natural fiber clothing to better protect yourself from the hazards of an arc flash.

