

# Spot the Hazards



WORK **SAFE BC**

*“Safety is a core value and business priority”*

 **West Fraser**

# Spot the Hazards



The angle of the yellow car suggests a potentially hazard defect in the lift.

No emergency washing facility seems to be in the area.

- The worker appears to be working alone and is smoking in the workplace.
- The position the worker's in to lift the tire isn't ergonomic.
- The worker is positioned under the raised vehicle.

The minivan is running, as evidence by the daytime running lights; no venting system is available to safely redirect exhaust gases outdoors.

The fire extinguisher is on the floor.

An oil collection pan (possibly containing transmission fluid) is directly behind the worker.

The cylinder of compressed gas is not secured.

The air hose is a tripping hazard.

**WORK** **SAFE** **BC**

*"Safety is a core value and business priority"*

West Fraser