



# Maintaining Rigging Equipment

**To keep rigging equipment in good condition:**


Avoid exposure to extreme heat, cold, and unusually high or low humidity.



Avoid prolonged exposure to sunlight or UV light



Be aware of chemical exposure or chemically active environments.



Keep slings clean and free of debris but do not use solvents or degreasers on nylon, polyester, and synthetic fiber, or fiber core wire rope slings.

Use edge and cut protection when using equipment on edges or rough surfaces.



Store equipment out of the elements by either hanging them neatly or placing them in an appropriate rigging box.

*“Safety is a core value and business priority”*