

Spot the Hazards




WORK SAFE BC

"Safety is a core value and business priority"



Spot the Hazards



The fire extinguisher is missing a sign.

The arm of the welding extractor is swung away from the welding bench, indicating that it's rarely used. It's also close to the door, so there's a risk of a head injury.

This worker is about to ignite a torch, in a cluttered environment, without wearing gloves.

The respirator is discarded and adding to the clutter. It doesn't have the right type of cartridges for work with solvents and paint.

The painter isn't wearing a respirator and is not clean-shaven.

This worker is using a pedestal grinder in proximity to flammable chemical use.

The painter isn't wearing gloves, protective clothing, or a hard hat. His posture is also not ergonomically correct.

The electrical cable is lying across the equipment

There are open and empty solvent cans lying around.

The painter is wearing running shoes.

WORK SAFE BC

"Safety is a core value and business priority"

