

Spot the Hazards




WORK SAFE BC

"Safety is a core value and business priority"



Spot the Hazards



There should be a mid-rail and toe board on the scaffold.

There is a bucket near the edge.

There is a dangerous gap in the middle of the upper level platform

The worker doesn't have safe access to the lower or upper levels of the scaffold (they would have to crawl through the brace and guard rails to reach it).

The access ladder is too short (it must be long enough to project approximately 1 m (3 ft.) above the upper landing to which it provides access).

Worker isn't wearing any fall protection.

The lower level platform is unfinished. There must be a guardrail present in order to use it.

The scaffold has a lockout tag, indicating that it shouldn't be used.



"Safety is a core value and business priority"

