PREVENTING INCIDENTS: PROPER STORAGE AND USE



Avoid exposure to extreme temperatures.

Be aware of chemical exposure or chemically active environments.

Avoid prolonged exposure to sunlight or UV light.

 Use edge and cut protection when using equipment on edges or rough surfaces.

Keep slings clean and free of debris but DO NOT use solvents or degreasers on nylon, polyester, synthetic fiber or fiber core wire rope slings.

To ensure rigging equipment is maintained in good working order, store it out of the elements by either hanging it neatly or placing it in an appropriate rigging box.



West Fraser Mills Ltd.

