

Contractors and PPE

Contractors must adhere to the same PPE standards as payroll West Fraser employees.

Contractors are responsible for supplying their own PPE.

At times, respiratory, chemical resistant, etc. may be required, but the following PPE is mandatory at all times when on site.

White hard hat



If hair is longer than shoulder-length, it must be tied up. and tucked to not pose as a hazard.

Safety eyewear



CSA approved glasses with side shields.
Eyewear protection must be appropriate to work being performed.

High visibility apparel



Cariboo Pulp requires that a high visibility vest is worn travelling to and from the parking locations onto the mill site and at all times while onsite

Safety footwear



Steel-toed safety footwear to be a minimum of 6-inches in height and lace-up style.

Gloves



At minimum, general purpose gloves. Gloves must be appropriate to work being performed

No watches or jewelry



“Safety is a core value and business priority”