

Spot the Hazards



WORK SAFE BC

"Safety is a core value and business priority"



Spot the Hazards



The entry permit hasn't been filled out or signed, and is missing atmospheric testing data.

The worker is using a wrench to tighten what looks like a propane canister. Containers of fuels such as gasoline or propane should not be taken into a confined space.

This worker is breaking protocol by crossing the plane of entry, they're potentially breathing in toxic air by having their face over the hole.

Lifting equipment is present but not set up, and therefore would not be helpful in an urgent emergency.

There's a rope but it's not set up for rescue purposes. The excess rope at the bottom is a tripping hazard.

This worker is not wearing a hard hat.

The mechanical fan system is located inside the confined space and not connected to the ducting; if it's turned on, it will only create turbulence in the space and will not provide fresh air. It is also a potential ignition source

The ventilation duct is not connected to the confined space or the mechanical fan system



"Safety is a core value and business priority"

